


Please route to:

☐ Service	☐ Init.
☐ Sales	☐
☐ Parts	☐



Date: November, 2006

No. 2006-06(W)

MODELS: 2007 Evinrude® E-TEC® 60°V4
115 HP Models

SUBJECT: Engine Software Update

Dear Evinrude/Johnson® Dealers:

This communication is to inform Evinrude and Johnson dealers of an important EMM software update.

AFFECTED MODELS

60°V4 Models	Serial Numbers
115 HP	Below 5176380

Please contact customers who have purchased the affected outboards and request they schedule this important warranty update. Affected outboards in stock **MUST** have the update software installed **before** delivering to customers.

DESCRIPTION

The update software has the following benefits:

- Enhanced oil management
- Improved start-up
- Increased outboard durability and engine life
- Improved engine run quality at IDLE and throughout the entire RPM range

INSPECTION

Remove the engine cover and inspect EMM for software update as shown. If the marking is present in the location shown, the update software has already been installed.



1. Mark

005510

PROCEDURE

If the update software is required, go to the DealerPort® website to download the necessary file. Dealers **without** DealerPort can send an e-mail requesting the new software.

Log into DealerPort.

Click **Engine Software**.



1. Engine Software link

005511

Click **Windows & PDA Maps**.



Scroll to the list of software part numbers and locate the appropriate Software P/N, based on the horsepower and model type.

Horsepower and Model Suffix	Software P/N	Revision (PCN)
115 HP "SUC"	3030352	93784

Click **Get Map**.

After downloading the file and opening it, the program will place the Engine Map files in three locations for use with *Evinrude Diagnostics* (EV DIAG), PDA and PDC Diagnostics software.

IMPORTANT: Do not change the default path from C:\ when the file is unzipped.

If you do not have DealerPort, e-mail a request for the software to bmca.techsvc@brp.com. In the e-mail subject line, you **must** reference "E-TEC 115 HP 60°V4 Software Map."

Identification Procedure

Outboards with updated software must be easily identified.

Use a BLACK permanent marker to mark the *EMM* as shown below to indicate updated software has been installed.



1. Mark

005510

IMPORTANT: It is not necessary to perform timing verification after this software is loaded.

DEALER RESPONSIBILITY

Please contact all of your customers who have purchased these outboards and request they return their outboards to your dealership for this service. Refer to "AFFECTED MODELS" on page 1.

ADDITIONAL INFORMATION

ONLY Authorized servicing Dealers may perform the software update.

Warranty claims can be filed on *DealerPort* using the following information:

- Flat Rate Code – **EM01**
- Failing Part Number – **9999972**
- Customer Comment Code – 239
- Bulletin Number – 2006-06(W)

Flat Rate Labor Allowance:

- Replacement – **0.5 hours**

DO NOT request other labor or parts on the warranty allowance request for this warranty campaign.

Dealers without *DealerPort* can submit a standard warranty claim form.

Labor will be paid in accordance with the established warranty labor rates listed in the current dealer warranty database.

BRP will credit dealers for repairs performed up to 12 months from the date this bulletin is issued. The proper return address is:

Mailing Addresses:

- **U.S. Dealers only** — The address is:

Bombardier Recreational Products
Evinrude/Johnson Dealer Support Services
250 Sea Horse Drive
Waukegan, IL 60085

- **Canadian Dealers** — The address is:

Bombardier Recreational Products Inc.
Attn: Service Department
1789 Stenson Boulevard
Peterborough, ON Canada K9J7B6

- **Dealers Outside North America** — Contact regional office.

For additional information, U.S. and Canadian dealers can call 1-800-888-4662. Dealers outside North America can call their regional office.