



OE TST - 2007 & Earlier Inline EMM Part Number & Software Determination (OE-35-2013)_000101800_TST84Y014S00_en

[Printable Version](#)

Rate This Article

(Average Rating: 3)

Language

English ▼

[Show Properties](#)

Summary:

Count the wires on the oil pump to determine what software should be loaded in the EMM when the EMM is non-functional.

Type:

General

TST Detail:

Scenario: EMM is dead-no communication-dealer needs to return EMM to Beloit for replacement. By counting the wires on the oil pump the dealer can determine what software needs to be loaded in EMM. Use chart below for EMM part Number & software version/revision. Also refer to P&A bulletin 2011-02P.

				
			6 Wire Oil Pump	5 Wire Oil Pump
Model Year	HP	EMM Part	Version - Revision #	Version - Revision #
2004-2005	40	586759	3030401-97227	3030401-97248
2004-2005	50	586759	3030332-97230	3030403-97251
2006-2007	40	586759	3030369-97229	3030402-96492
2006-2007	50	586759	3030370-97231	3030404-96494
2006-2007	60	586862	3030371-97233	3030406-96496
2004-2007	75	586759	3030372-90187	3030407-96497
2004-2007	90	586759	3030373-96905	3030408-96498

Attachment:

First Published By: on 2014-10-23

Last Modified By: on 2016-10-30